

1/24





FIG. 1A

FIG. 1B



3/24

FIG.2

200
↙

Core Systems
ITS Login

Welcome to the Core Systems
Issue Tracking System.
This is a secure site which requires a login.

Enter your login and password 202

Login 204

Password 206

☒ Remember this login and password
on this computer. 208

210

FIG.3A




FIG.3B




FIG.3C

360

Core Systems

Issue Tracking System

Administration

Home

Project Stats

Site Usage

Log

Project:

Project A

Search Defects:

Welcome: doug_k

(Super User)

View

Submit

Assign

Resolve

Close

Modify

Project

Report

Add New User

Login:

362

Name:

364

Email Address:

366

Phone:

368

Password:

370

Confirm Password:

371

374

User Access Level

376

☒ Issue Submitter

378

☐ Member of Project

380

☐ Super User

382

Add

Cancel

384

7/24

FIG.3D

390

304

Administration

Home

Project Stats

Site Usage

Log

Project: Project A

Search Defects:

Welcome: doug_k (Super User)

Core Systems

Issue Tracking System

View Submit Assign Resolve Close Modify Project Report

Show Active User

391

397

Print Export

No.	User Name	Phone Number	Current Projects	Last Access
1	Alan L	(970) XXXX 074	Project A	-----
2	Ayonna B	(707) XXXX 644	Project B	Apr 9 2003 4:17pm
3	Bill S	(970) XXXX 832	Project A	Jun 5 2003 1:48pm
-----	-----	-----	-----	-----
32	Jim A	(970) XXXX 272	Project D	-----
33	Terrance G	(707) XXXX 618	None	-----

392

393

394

395

396

8/24

FIG. 4




FIG.5

500

Administration Home Project Stats Site Usage Log

Project: Project E

Search Defects:

Welcome: doug_k (Super User)

Core Systems

Issue Tracking System 502

View Submit Assign Resolve Close Modify Project Report

Show New Issues Owned By << No One >> 522

Sorted By Severity Submitted By << Anyone >> 506

504

508

Print Issues 522

510

Severity	Summary	Submitter	Submit Date	Issue ID
4	Replace text that refers to Colby with new Agilent part number	kevin_e	Jan 08, 2003 9am	ITS000004730
4	Jitter Gen, enhancement suggestions	al_l	Jan 15, 2003 4pm	ITS000004757
0	Convenience PN graph needs 10 db/decade line	kevin_e	Oct 09, 2002 3pm	ITS000004485
0	Generation results needs to include spur-	kevin_e	Oct 09, 2002 3pm	ITS000004486

512

514

516

518

520

FIG.6

600

Administration

Home

Project Stats

Site Usage

Log

Project:

Project E

Search Defects:

Welcome: doug_k

(Super User)

Core Systems

Issue Tracking System

331

View

Submit

Assign

Resolve

Close

Modify

Project

Report

330

Show

Assigned Issues

Owned By

<< Anyone >>

Print Issues

Sorted By

Severity

Submitted By

al_k

Severity	Summary	Submitter	Owner	Issue ID
6	K82 ACM start-up error/lock-out if K82 not present	al_k	salvador_o	ITS00004980
5	Jitter Xfr: printout doesn't match displayed plot	al_k	salvador_o	ITS00004579
4	Jitter Xfr: zoom feature doesn't scale correctly	al_k	salvador_o	ITS00004240

616

630

FIG. 7

Administration

Home

Project Stats

Site Usage

Log

Project: Project E

Search Defects:

Welcome: doug_k (Super User)

View

Submit

Assign

Resolve

Close

Modify

Project

Report

330

Core Systems

Issue Tracking System 332

Issue: ITS00003704

Project: Project E

Submitted: Aug 12, 2002 2pm

History

Summary: Quadrature method can set quad. for 2.5G, but it can't set quad. for 10G (ITU)

State: Closed 716 Area: Measurement science

Closed on: Sep 05, 2002 11am 718 Resolution: Code

Version Found: Integration 3 720 Version Fixed: Integration 3

Submitter: jayson_r 722 Submitter Phone: (970) XXXXX

Owner: sheeyun_p 724 Owner Phone: (970) XXXXX

Severity (Frequency + Consequences - Workaround) = 5 + 4 - 0 = 9

Frequency: 5: Occurs in required usage, very common or pervasive

Consequences: 4: Hang or unexpected exit, damaged or lost files, substantial loss of work

Workaround: 0: No reasonable workaround

Detail Description

In the ITU OC-48, ITU OC-48 FEC specs. I can run a transfer measurement all the way through. and everything works properly However, when I try to run an ITU OC-192 or ITU OC-192 FEC transfer measurement. I get a slew of errors, all originating back to an error that states:

728

730

Owner Notes

See issue # ITS00003662. The LNA gain settings were not being factored out of the voltage readings from the test set. This caused the quadrature readings to be overly sensitive.

732

Close Notes

SOI (09/05/02) : Verified that no quadrature errors are generated for ITU OC-192 and ITU OC-192 FEC the measurements ran to completion (using loopback)

734

736

Modify Issue

Print...

Delete Issue

740

738

12/24

FIG. 8

History for Issue ITS00003704				
Action	Date		User	
Submit	Aug 12 2002	2:09 pm	jayson_r	
Assign	Aug 12 2002	2:40 pm	kevin_e	
Resolve	Aug 13 2002	2:35 pm	sheeyn_p	
Close	Sept 5 2002	11:12 am	salvador_o	
Update	Sept 5 2002	6:18 pm	salvador_o	

808

800

802

804

806

FIG. 9

900

Core Systems
Issue Tracking System

331

Administration Home Project Stats Site Usage Log

Project: Project E

Search Defects:

Welcome: doug_k (Super User) 334

View Submit Assign Resolve Close Modify Project Report } 330

Issue: ITS00005293 Submitter: jayson_r State: Submit

904Summary: Software Locks Up.

906Phase Found: QA Test 914Integration 3

910Area: Measurement Science 916Unknown

912Priority: << Undefined >>

920

Severity (Frequency + Consequences - Workaround) = (5+4-0)=9

Frequency 5: Occurs in required usage, very common or pervasive 921

Consequences 4: Hang or unexpected exit, damage or lost files, substantial loss of work 923

Workaround 0: No reasonable workaround 925


922Detail Description
Software locks up upon implementing PCC methodology

930Attachments

932Add

938Submit

FIG. 10



15/24

FIG. 11

1100

Administration Home Project Stats Site Usage Log

Project: Project E

Search Defects:

Welcome: doug_k (Super User)

334 333

View Submit Assign Resolve Close Modify Project Report } 330

Core Systems
Issue Tracking System

1102 Issue: ITS00003704 Submitter: jayson_r State: Closed

1104 Summary: Quadrature method can set quad for 25G but it can't set quad for 10G (ITU)

1106 Phase Found: QA Test 1114

1108 Resolution: Code 1116

1110 Area: Measurement Science

1112 Priority: << Undefined >> 1118

1120

Severity (Frequency + Consequences - Workaround) = (5+4-0)=9

Frequency 1121 5: Occurs in required usage, very common or pervasive

Consequences 1123 4: Hang or unexpected exit, damage or lost files, substantial loss of work

Workaround 1125 0: No reasonable workaround

1122 Detail Description 1126

1124 Workaround 1128

1130 Attachments

1132 Add...

1134 Delete...

1136 Open...

1138 Update 1140 Cancel 1142 Delete Issue

FIG. 12

1200

Administration Home Project Stats Site Usage Log

Project: Project F 326

Search Defects:

Core Systems 335 Issue Tracking System 336 337

Welcome: doug_k (Super User) 334 333

View Submit Assign Resolve Close Modify Project Report 330

1203

Project R&D Engineers

<< No One >> Add >> 1202 1210

1206 1204 << Remove 1208 1214

Project Administrators (can modify project)

<< No One >> Add >> 1218 1226

1222 1220 << Remove 1224 1230

Versions

1234 1236 1.0.1.0. 1240

<< Unknown >> << Remove 1238 1242

Set Default 1244

Project QA Engineers

<< No One >> Add >> 1216 1212

1211 << Remove 1214

Project Viewers (read-only access)

<< No One >> Add >> 1226 1228

1227 << Remove 1230

Areas

1247 1248 Add >> 1246

<< Unknown >> << Remove 1254

Set Default 1256

Characterization Configuration Correction Documentation 1250

Email Notification

☒ Notification Enabled

Notify Submitter

☒ Issue received

☒ Issue assigned

☒ Issue resolved

☒ Issue closed

☒ Issue modified

☒ Issue (un)postponed

Apply Notification Settings

Notify Administrators

☒ Issue submitted

☐ Issue assigned

☐ Issue resolved

☐ Issue closed

☐ Issue modified

☒ Issue (un)postponed

Notify Assigned Engineer

☒ Issue assigned

☒ Issue modification

Notify QA Engineers

☒ Issue resolved

☐ Issue closed

☒ Issue (un)postponed

FIG.13

AdministrationHomeProject StatsSite UsageLog

Project:Project C

Search Defects:

Core Systems

Issue Tracking System

335

336

337

Welcome: doug_k
(Super User)

338

330

ViewSubmitAssignResolveCloseModifyProjectReport

1302

ShowAssigned Issues

Owned By<<Any One>>

1306

Print Report

1304

Sorted BySeverity

Submitted By<<Any One>>

1308

Issue ID	Severity	Summary	Submitter	Actions
ITS00004509	5	Add Self Test	tmcb	ModifyPostponeDuplicateForwardDelete
ITS00004514	3	Add graphical path configuration utility	tmcb	ModifyPostponeDuplicateForwardDelete
ITS00002081	2	Record and track switch cycle counts	mike_o	ModifyPostponeDuplicateForwardDelete

1300

1309

1310

1312

1314

1316

1318

FIG. 14

Administration Home Project Stats Site Usage Log

Project: Project B

Search Defects:

Welcome: doug_k (Super User)

Core Systems Issue Tracking System

View Submit Assign Resolve Close Modify Project Report

1402 Show Submitted Issues

1404 Analyze By Date Submitted

1406 Resolved via <<Any Resolution>>

1408 Format List

Having From Through Sorted By

Any Severity

Jun 6

Oct 6

Date Submitted

1410 Print Report

2002

2002

1416

1418

340 Listed Issues: Average Severity

Date Submitted	Issue ID	Summary	Submitter	Owner	Severity
Jan 06, 2002	ITS000002815	Can't find local PNA if Building LAN enabled and other system with same PNA name	mic_v	mark_o	8
Jan 06, 2002	ITS000002816	Installer fails to install start.exe in the GS9200\bin directory	mic_v	max_re	9
Jan 06, 2002	ITS000002832	GUI allows user to close it while a testplan is running. No information or recourse offered	mic_va	evan_i	9
Jan 06, 2002	ITS000002834	Running SysCal testplan, used F5 key for OK in operator message = Run-time error 91	mic_va	evan_i	9

FIG. 15 1500

Administration Home Project Stats Site Usage Log

Project: Project B

Search Defects:

Core Systems
Issue Tracking System

Welcome: doug_k
(Super User)

View Submit Assign Resolve Close Modify Project Report

1502 Show Submitted Issues Having Any Severity 1510 Print Report 1512

1504 Analyze By Date From 2002 2002 1514

1506 Resolved via <<Any Resolution>> Through

1508 Format Chart-Line Plot By Issue Count 1516




FIG. 16




FIG. 17

1700

Administration Home Project Stats Site Usage Log

Project: Project C

Search Defects:

Welcome: doug_k (Super User)

View Submit Assign Resolve Close Modify Project Report

1702 Show Resolved issues Having Any Severity Print Report 1708

1704 Analyze By Project Team

1706 Format Chart-Column

Project C Resolved Issues
By Project Areas




FIG. 18

1800
Core Systems
Issue Tracking System

Administration Home Project Stats Site Usage Log
Project: Project D
Search Defects: 326

Welcome: doug_k
(Super User)

View Submit Assign Resolve Close Modify Project Report
1802 Show Assigned issues Having Any Severity Print Report 1808


1804 Analyze By Project Team
1806 Format List

Project Member	Outstanding Assigned Issues	Average Severity
dave_w:	21	4.43
dave_d	12	3.58
jerry_m	5	5.20
jim_b:	8	4.12
Total	46	4.24

1812 1814 1816

22/24 1810

FIG. 19



328

FIG.20

2000

Core Systems
Issue Tracking System

Administration

Home

Project Stats

Site Usage

Log

Project:

Project C

Search Defects:

dave

Welcome: doug_k

(Super User)

View

Submit

Assign

Resolve

Close

Modify

Project

Report

Results of search defects for "dave" (79 records found)

Issue ID	Summary	Severity	Submitter	Owner	State
ITS000003640	XOA: Enhancementrequest: need to expose Results operations	6	dave_w	dave_w	Resolved
ITS000003721	Operations: Enable Trace and Enable Results: file path has extra slashes	2	dave_w	jerry_m	Resolved
ITS000004588	Access denied error if Station Confi is not writeable by user 0.9	8	dave_g	sheeyun_p	Resolved
ITS000004599	Sequence adapter: Can not call sequences from multiple files	8	lou_m	dave_w	Assigned

2002

2004

2006

2008

2010

2012